



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 10

1200 Sixth Avenue  
Seattle, WA 98101

NOV 01 2000

Reply To

Attn Of: WCM-128

**CERTIFIED MAIL - RETURN RECEIPT REQUESTED**

**NOTICE OF CASE CLOSURE**

Ms. Amy Fuller  
Total Reclaim, Inc./Ecolights Northwest  
P.O. Box 24996  
4400 4th Avenue South  
Seattle, Washington 98134

Dear Ms. Fuller:

This concerns the November 24, 1998, Environmental Protection Agency (EPA) inspection which was conducted at the Total Reclaim, Inc. facility which also includes the company subsidiary, Ecolights Northwest, located in Seattle, Washington. The inspection was conducted by Ms. Eileen Hileman, of the Office of Environmental Assessment, to determine compliance with the federal PCB (polychlorinated biphenyl) regulations which were promulgated pursuant to the Toxic Substances Control Act (TSCA).

The following concerns need to be corrected:

(1) The fifty-five gallon drum was marked with a PCB label, however, the entrances to the decommissioning area where the storage for disposal drum was kept are not marked with PCB labels.

(2) Remove combustible materials stored around the PCB drum disposal area.

There were no other violations found during the inspection for both facilities and we consider this matter closed when the above mentioned concerns are addressed. We thank you for your cooperation in this matter.

If any additional information is required, please contact me at (206) 553-6693.

Sincerely,

Daniel L. Duncan  
Regional PCB Program Manager  
Solid Waste and Toxics Unit

USEPA REG



0001008

Reply To  
Attn Of: WCM-128

**CERTIFIED MAIL - RETURN RECEIPT REQUESTED**

**NOTICE OF CASE CLOSURE**

Ms. Amy Fuller  
Total Reclaim, Inc.  
P.O. Box 24996  
4400 4th Avenue South  
Seattle, Washington 98134

Dear Ms. Fuller:

This concerns the November 24, 1998, Environmental Protection Agency (EPA) inspection which was conducted at the Total Reclaim, Inc. facility which also includes the company subsidiary, Ecolights Northwest, located in Seattle, Washington. The inspection was conducted by Ms. Eileen Hileman, of the Office of Environmental Assessment, to determine compliance with the federal PCB (polychlorinated biphenyl) regulations which were promulgated pursuant to the Toxic Substances Control Act (TSCA).

The following concerns need to corrected:

(1) The fifty-five gallon drum was marked with a PCB label, however, the entrances to the decommissioning area where the storage for disposal drum are kept are not marked with PCB labels.

(2) Remove combustible materials stored around the PCB drum disposal area.

There were no other violations found during the inspection for both facilities and we consider this matter closed when the above mentioned concerns are addressed. We thank you for your cooperation in this matter.

bcc: Eileen Hileman

CONCURRENCES					
INITIALS	<i>R Nye</i>	Groupwise			
NAME	Raymond Nye	Eileen Hileman			
DATE	10/31/00				